

HP Laptop Wireless Failure Investigation

Finkelstein Thompson LLP is investigating allegations that certain HP laptops experience unusually high rates of wireless connection failures.

Finkelstein Thompson LLP is investigating allegations that certain model laptops manufactured by HP are experiencing unusually high rates of wireless connection failures. The HP model numbers allegedly affected are the HP Pavilion dv2000 series, the HP Pavilion dv6000 series, the HP Pavilion dv9000 series, the HP Pavilion tx1000 series, the Compaq Presario V3000 series, and the Compaq Presario V6000 series. HP has continued to market and sell these defective laptops despite allegedly knowing, since at least as early as 2007, that these models carry wireless device defects.

If you have purchased an HP laptop which is experiencing wireless connection failures and wish to discuss your rights and interests in this matter, please contact our Washington, D.C. office toll-free at (877) 337-1050 or by email at contact@finkelsteinthompson.com .